










How to Perform a PDI Test by using 1D/2D VIN Barcode Scan














CONTACT US

TECH SUPPORT - USA
1-877-453-3265 English
support.usa@e-xteq.com

HOURS OF OPERATION (EST)
Monday - Friday: 8 am - 8 pm

Comprehensive support also available
through www.e-xteq.com

How to Perform a PDI Test by using Manual Battery Selection



CONTACT US

TECH SUPPORT - USA
1-877-453-3265 English
support.usa@e-xteq.com

HOURS OF OPERATION (EST)
Monday - Friday: 8 am - 8 pm

Comprehensive support also available
through www.e-xteq.com